



IECEX Facility Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION
IEC Certification System for Explosive Atmospheres
for rules and details of the IECEX Scheme visit www.iecex.com

FAR Ref. No.: **NL/DEK/FAR21.0006/02** Page 1 of 1
Issuing ExCB: **DEK - DEKRA Certification B.V.** Date of issue: **:2023-12-01**
Status: **Issued**

Audit date: **2023-11-24** Valid Until: **2026-11-24**

Location(s) audited: **KSB Service Belgium NV**
Kluizenhof 35
St-Gillis-Waas B-9170
Belgium

Service Facility: **KSB Service Belgium NV**
Kluizenhof 35
St-Gillis-Waas B-9170
Belgium

Details of change: **Initial audit due to changed repair facility location.**

Type of work Covered by Service Facility: **Repair, overhaul and maintenance of non-electrical equipment Ex h, mainly pumps, mixers and propellers, non-electrical type of protection constructional safety "c", control of ignition sources "b", liquid immersion "k".**

On-site services limited to inspection, alignment, mounting, dismantling and change of the mechanical seal cartridge.

Related FARs:
[NL/DEK/FAR21.0006/00](#) [NL/DEK/FAR21.0006/01](#)

Related IECEX Service Facility Certificates:
[IECEX DEK S0048 Issue 1](#)

Comments: **KSB Wavre and KSB St-Gillis-Waas have the same legal entity.**